CERAMIC COATING CARE CHECKLIST

The following checklist assumes you are using the "Multiple Wash Mitt Method" with a foam gun or cannon. Otherwise, use the "Two Bucket Method". Use two 5-gal buckets, one with soapy water and the other with rinse water. Insert Grit Guards in both buckets to capture dirt particles. Use Grit Guard Washboard in rinse bucket to scrub mitt and remove dirt.

SUPPLIES

PH BALANCED SOAP FOAM GUN OR CANNON MULTIPLE WASH MITTS PRESSURE WASHER OR HOSE MULTIPLE MICROFIBER TOWELS MICROFIBER DRYING TOWELS LEAF BLOWER x2 5 GALLON BUCKETS (FOR 2-BUCKET) x2 GRIT GUARDS (FOR 2-BUCKET) DRYING AID - PAINT HERO GRIT GUARD WASHBOARD (FOR 2-BUCKET) CERAMIC SPRAY - BEAD HERO

STANDARD OPERATING PROCEDURES

AVOID WASHING DURING 1ST WEEK 6. FOAM, WASH & RINSE TRUNK LID AVOID DRIVING IN RAIN DURING 1ST WEEK 7. FOAM, WASH & RINSE DRIVER SIDE APPLY TEMP PROTECTION FOR 1ST WEEK 8. FOAM, WASH & RINSF PASSENGER SIDE MAINTENANCE WASH PROCEDURES 9. FOAM, WASH & RINSE FRONT 1. PRE-RINSE TO BLAST LOOSE DIRT 10. FOAM, WASH & RINSE REAR 11. RE-RINSE ENTIRE VEHICLE 2. SPRAY FOAM & LET DWELL (3 MIN) 3. RINSE FOAM-LOOSENED GRIME 12. BLOW DRY STANDING WATER 4. FOAM, WASH & RINSE ROOF/WINDOWS 13. DRY WITH TOWELS & DRYING AID 5. FOAM, WASH & RINSE HOOD 14. APPLY SPRAY CERAMIC (EVERY 3-4 MONTHS)