WATER SPOT REMOVAL CHECKLIST

The following checklist covers water spot removal procedures for both topical water spots (mineral deposit stains on top of paint) and etched water spots (imprint rings in the paint).

SUPPLIES

- WATER SPOT REMOVER COMPOUND, POLISH & AIO
- CLEAN MICROFIBER TOWELS CUTTING, POLISHING & FINISHING PADS
- ORBITAL POLISHER CERAMIC COATING

STANDARD OPERATING PROCEDURES

- ENSURE ENGINE IS COOL TO TOUCH IDENTIFY & DOCUMENT WATER SPOTS
- MOVE VEHICLE OUT OF DIRECT SUNLIGHT ENSURE VEHICLE IS WASHED & DRIED

FOR TOPICAL WATER SPOTS

- 1. SPRAY WATER SPOT REMOVER ON SPOTS 1. TEST LIGHT POLISH WITH POLISHING PAD
- 2. LET DWELL 3 MIN WITHOUT DRYING
 2. EVALUATE RESULTS WITH STRONG LIGHT
- 3. WIPE AWAY IN OVERLAPPING MOTION 3. INCREASE AGGRESSION LEVEL IF NEEDED
- 4. FLIP TOWEL AND BUFF SURFACE
 4. FOLLOW WITH POLISHING STEP IF NEEDED
- 5. REPEAT TO ALL AFFECTED BODY PANELS 5. REPEAT TO ALL AFFECTED BODY PANELS
 - 6. APPLY CERAMIC COATING TO PROTECT

FOR ETCHED WATER SPOTS